

Табела Т.5. Критичне вредности за Grubbs-ов тест (G – тест) G -табела

N/α	0,1	0,075	0,05	0,025	0,01		N/α	0,1	0,075	0,05	0,025	0,01
3	1,15	1,15	1,15	1,15	1,15		53	0	0	2,981	3,151	999
4	1,42	1,44	1,46	1,48	1,49		54	0	0	2,988	3,158	999
5	1,60	1,64	1,67	1,71	1,75		55	0	0	2,995	3,165	999
6	1,73	1,77	1,82	1,89	1,94		56	0	0	3,002	3,172	999
7	1,83	1,88	1,94	2,02	2,1		57	0	0	3,009	3,179	999
8	1,91	1,96	2,03	2,13	2,22		58	0	0	3,016	3,186	999
9	1,98	2,04	2,11	2,21	2,32		59	0	0	3,023	3,193	999
10	2,03	2,1	2,18	2,29	2,41		60	0	0	3,03	3,20	999
11	2,09	2,14	2,23	2,36	2,48		61	0	0	3,036	3,206	999
12	2,13	2,2	2,29	2,41	2,55		62	0	0	3,042	3,212	999
13	2,17	2,24	2,33	2,46	2,61		63	0	0	3,048	3,218	999
14	2,21	2,28	2,37	2,51	2,66		64	0	0	3,054	3,224	999
15	2,25	2,32	2,41	2,55	2,71		65	0	0	3,06	3,23	999
16	2,28	2,35	2,44	2,59	2,75		66	0	0	3,066	3,236	999
17	2,31	2,38	2,47	2,62	2,79		67	0	0	3,072	3,242	999
18	2,34	2,41	2,50	2,65	2,82		68	0	0	3,078	3,248	999
19	2,36	2,44	2,53	2,68	2,85		69	0	0	3,084	3,254	999
20	2,38	2,46	2,56	2,71	2,88		70	0	0	3,09	3,26	999
21	0	0	2,58	2,73	2,91		71	0	0	3,095	3,265	999
22	0	0	2,60	2,76	2,94		72	0	0	3,1	3,27	999
23	0	0	2,62	2,78	2,96		73	0	0	3,105	3,275	999
24	0	0	2,64	2,8	2,99		74	0	0	3,11	3,28	999
25	0	0	2,66	2,82	3,01		75	0	0	3,115	3,285	999
26	0	0	2,68	2,84	999		76	0	0	3,12	3,29	999
27	0	0	2,70	2,86	999		77	0	0	3,125	3,295	999
28	0	0	2,72	2,88	999		78	0	0	3,13	3,3	999
29	0	0	2,73	2,9	999		79	0	0	3,135	3,305	999
30	0	0	2,75	2,91	999		80	0	0	3,14	3,31	999
31	0	0	2,76	2,93	999		81	0	0	3,144	3,314	999
32	0	0	2,78	2,95	999		82	0	0	3,148	3,318	999
33	0	0	2,79	2,96	999		83	0	0	3,152	3,322	999
34	0	0	2,81	2,97	999		84	0	0	3,156	3,326	999
35	0	0	2,82	2,98	999		85	0	0	3,16	3,33	999
36	0	0	2,83	2,992	999		86	0	0	3,164	3,334	999
37	0	0	2,84	3,004	999		87	0	0	3,168	3,338	999
38	0	0	2,85	3,016	999		88	0	0	3,172	3,342	999
39	0	0	2,86	3,028	999		89	0	0	3,176	3,346	999
40	0	0	2,87	3,04	999		90	0	0	3,18	3,35	999
41	0	0	2,88	3,05	999		91	0	0	3,183	3,353	999
42	0	0	2,89	3,06	999		92	0	0	3,186	3,356	999
43	0	0	2,90	3,07	999		93	0	0	3,189	3,359	999
44	0	0	2,91	3,08	999		94	0	0	3,192	3,362	999
45	0	0	2,92	3,09	999		95	0	0	3,195	3,365	999
46	0	0	2,928	3,098	999		96	0	0	3,198	3,368	999
47	0	0	2,936	3,106	999		97	0	0	3,201	3,371	999
48	0	0	2,944	3,114	999		98	0	0	3,204	3,374	999
49	0	0	2,952	3,122	999		99	0	0	3,207	3,377	999
51	0	0	2,967	3,137	999		100	0	0	3,21	3,38	999
52	0	0	2,974	3,144	999							

 N – број мерења и α – ниво поузданости